





0935



v010
21.02.2022
D. P.
[cm]




vinci
play



[cm]





vinci
play




x2
 1 h


 48h
 x4 0,06 m³



092128
x2



092131
x1









092110
x3

6x	10x20wl
6x	10ppl
1x	E244
1x	E245
1x	V002

[cm]

vinci
play







092128

092131



092128

1x **E244**



6x **10x20wl**

6x **10ppl**





1x **E245**

[cm]




vinci
play



Part No:
000000-
00000

000000-00000



[cm]

vinci
play