







WD1436





v017
19.02.2022
A. D.
[cm]



vinci
play






[cm]








vinci
play







[cm]









vinci
play




		PLYWOOD / HDPE		HPL	
136x	8x50 sxi	2x	WD28(s1)	2x	WD29(s1)
2x	6x50 sxs	2x	WD113(s6)	2x	WD114(s6)
2x	E34(K1,K3)	2x	WD33	2x	WD34
2x	E35(K2)	2x	WD63	2x	WD64
1x	E88(K2,K3)	2x	WD72	2x	WD73
2x	WD2	2x	WD74	2x	WD75
1x	WD14-4	1x	WD94	1x	WD95
2x	Z18	1x	WD132	1x	WD132
1x	V001	1x	WD134	1x	WD135
		2x	WD182	2x	WD181








[cm]







vinci
play



[cm]






vinci
play




[cm]





vinci play



WD2




8x50 sxi






[cm]







vinci
play



PLYWOOD HPL
WD33 ○ WD34



8x50 sxi




PLYWOOD HPL
WD25 ○ WD26

8x50 sxi





[cm]



vinci
play






PLYWOOD HPL
WD28 (S1) **WD29**
 PLYWOOD HPL
WD113 (S6) **WD114**



[cm]



vinci
play



[cm]




vinci
play



V001

Part No:
000000-
00000

000000-00000



[cm]



vinci
 play