







1638



v011
19.02.2022
A. D.
[cm]





vinci
play




[cm]

vinci
play




[cm]


vinci
play




E90




E1








A.






B.




C.



	K2, K3
M10x120 x8	
NOT INCLUDED	

[cm]

vinci play



[cm]


vinci
play



164104
x6




162100
x6




162101
x10




162103
x6




162102
x14




NK_kotw_1
x12




165103
x1



165112
x2



165111
x2




164100
x2




164102
x1




164103
x1




163100
x1



163102
x1



163103
x6




163104
x4





16x	E1
2x	E66
2x	E74
3x	E90
2x	E91
2x	E92
20x	E93
1x	E94
6x	E96
2x	E98
2x	E99
4x	WD52
1x	V002

[cm]

vinci
play







E74



E98




E1



E96



E93

E92







[cm]

vinci play



[cm]



vinci
play



M10x120 x8	Ø10
NOT INCLUDED	

[cm]

vinci play



1x V002

[cm]

vinci
play