





# WD1426



v015  
25.11.2021  
W.G.  
[cm]





vinci  
play



[cm]


vinci  
play



[cm]





vinci  
play



[cm]



vinci  
play



[cm]




2h




vinci  
play




14712090  
x2




14715990  
x2




142101  
x4




142174  
x4



142175  
x4








i96  
x8






141151  
x8

		PLYWOOD		HPL	
56x	8x50 sxi	8x	WD216	8x	WD215
4x	WD1				
1x	V001				







WD1







8x50 sxi



8x50 sxi




PLYWOOD WD216 HPL WD215




V001

Part No:  
000000-  
00000



[cm]



vinci play