




# 0499




v011  
13.01.2022  
B. K.  
[cm]

vinci  
play





[cm]

vinci  
play




[cm]



[cm]





vinci  
play



[cm]







vinci  
play



16x M10x120 (K2)  
16x M10x120 (K3)


**NOT INCLUDED**




[cm]

x2   
 2h   
   
 x4   
 0,06 m³   
 48h   
 K2/K3 x4 >0,02m³

vinci  
play



044114  
x1



044115  
x1






147\_130\_90  
x2







147\_159\_90  
x3




045192  
x1

<p>K1</p>  <p>042118 x4</p>	<p>K2</p>  <p>042166 x4</p>	<p>K3</p>  <p>042167 x4</p>
--	--	--

4x	WD1
34x	8x50 sxi
1x	E202
6x	i29
1x	V001











8x50 sxi

i29



V001






WD1


[cm]




vinci  
play





8x50 sxi



48h



E202




8x50 sxi

Part No:  
000000-  
00000

000000-00000

[cm]



vinci  
play