







RB2312





v010
17.11.2021
D. P.
[cm]

vinci
play



[cm]


vinci
play



[cm]



vinci
play










[cm]



vinci
play

K29



vinci play


[cm]



127680 A
x1



127670 B
x1










232113
x1



235101
x1

4x	8x50sxi
1x	231101
1x	126312
2x	12e005
2x	12e107
1x	23e046
1x	E86
2x	i429





2x 12e107








i429

i429

232113

[cm]





vinci
play



2x 12e005

[cm]

vinci
play



Part No:
000000-
00000

000000-00000

[cm]

vinci
play