



[cm]

vinci
play



	L
RB1385-20m	2465
RB1385-30m	3465
RB1385-40m	4465




	A [cm]	S [m ²]
RB1385-20m	2204	84,4
RB1385-30m	3192	124,0
RB1385-40m	4192	164,0

[cm]




vinci
play


20m



30m








40m



[cm]



vinci
play



	Y
RB1385-20m	1937
RB1385-30m	2937
RB1385-40m	3937

[cm]


x4
 3h

 48h
 K25
 x6 >0.06m³

vinci play



420H
x1



420B
x1




127186
x2




127189
x2




163109
x2



122109
2x









122108
2x














b588
x4

ST/INOX

1x	12e040
1x	E105
1x	12e038
1x	E107
1x	E108
1x	12e039
2x	12e037
2x	E134
1x	E206(20m)
1x	E207(30m)
1x	E208(40m)
1x	E209
1x	E210
1x	E211
1x	E212
1x	12e036
1x	042145
1x	041134
1x	042177
1x	042178
1x	i219
1x	i158
1x	V002



b588




12e036


[cm]




vinci play





12e037




12e040



12e039






E105






[cm]

vinci play




E107

E107





12e038



[cm]




vinci
play



E108



E134



E206

E207

E208

0,00

150


min 40

70kg


300

250

200




E209



E211






E212




E210

!!!


48h



E107




7




E107

[cm]



vinci play



A diagram illustrating the cleaning and maintenance process. It shows a spray bottle with a nozzle and the text "%00" (representing 100% disinfection). An arrow points to a hand being wiped with a cloth. A second arrow points to a rectangular label with the following text:


vinci
play
Art. No.
Year
202

Vinci Group Sp. z o.o.
Pogoda, ul. Kłobucka 8
05-016 Iłża-Łęka
POLAND
+48 42 253 24 00
www.vinci-play.com
www.hobby.com.pl

V002

Part No:
000000-
00000

A barcode with the number 000000-00000 printed below it. A sticker is shown being applied to the right side of the barcode area.



[cm]



vinci
play